Hercules Task 6.2 - Humidification methods Progress update



Installation of water pipes



February 2007

- Fresh water 2 outlet on engine
- Modification of central cooling water system
- Installation of spray pipes in fresh water 1 and 2